-		May 15, 2011	
Complet	*** ***	7 20, 2011	
Complete	engine major	overhaul up through Lycoming revision number 60294-7-4.	5300 - 20
6- ECI Cor	mnlete culinal	7-27-11 number 60294-7-4.	
	inpiece cylinger	assemblies rebuilt; 6-ECI Connecting rods rebuilt with new rod bolts and nuts	
All steel p	arts magnaflux	ed and increase the second muts	
	0	ed and inspected by ECI; Complete new gasket and seal kit;	
1- Aircraft	Specialties Lyc	oming standard crank; 1-Aircraft Specialties Lycoming standard camshaft	
Now Cum-		Specialties Lycoming standard camshaft	11
ivew Sube	rior Air Parts m	ain and crankshaft bearings	
Fuel injecti	on system com	mlata	
	:	plete overhaul by Airflow Performance with new injection lines	
All new ign	ition system co	mponents with fresh inspected and serviced magnetos	
Λ II		with resh inspected and serviced magnetos	
HII KNOWN A	AD's and SB's co	mplied with.	
		Texas Engine Service, Inc.	
		100 Meadow Dr.	
4		Georgetown,TX 78633-9556	
		Lit's E. Hancach	

## MAINTENANCE & SERVICE HISTORY

II:	DATE <u>G-17-05</u> A/C N# <u>6034 S</u> PROP SN# <u>DN 3501</u>	on Of Work	Authorized Signatures Repairman and Station Certificate Numbers
8	TT HR. 412,7 TTSMO 412,7	3000 000 000 000 000 000 000 000 000 00	
	THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH A VISUAL 100 HR INSPECTION PER FACTORY BOOKS AND		
	MANUALS AND IS RETURNED TO SERVICE IN AN AIRWORTHY CONDATION. REFUR TO PROP MANUAL& A/C MASTER RECORDS FOR PROP LUBE& MAINTANCE		
	PROP DUE FOR SHOP INSPECTION IN  HRS.		
	GEORGE B ROBINSON AP/ AI 2403885		
	3B Molinson		
		· · · · · · · · · · · · · · · · · · ·	
100	NOTE: Enter Compliance With All Applicable FAA A.D.'s	& Factory Service Bu	Illetins On Last Two Pages
			on Last Two Fages.